





USAARL REPORT NO. 77-1

MASS SPECTROSCOPIC ANALYSIS OF POLYETHER AND POLYURETHANE FOAM PLASTICS DEGENERATION IN THE SPH-4 HELMET

BY

Roderick J. McNeil, CPT, MSC Frank S. Pettyjohn, M.D., LTC, MC

US ARMY AEROMEDICAL RESEARCH LABORATORY Fort Rucker, Alabama 36362

US Army Medical Research and Development Command Washington, DC 20314

October 1976

Final Report



Approved for public reserve Distribution Unlimited

NOTICE

Qualified requesters may obtain copies from the Defense Documentation Center (DDC), Cameron Station, Alexandria, Virginia. Orders will be expedited if placed through the librarian or other person designated to request documents from DDC (formerly ASTIA).

Change of Address

Organization receiving reports from the US Army Aeromedical Research Laboratory on automatic mailing lists should confirm correct address when corresponding about laboratory reports.

Disposition

Destroy this report when it is no longer needed. Do not return it to the originator.

Distribution

This document has been approved for public release and sale; its distribution is unlimited.

Disclaimer

The findings in this report are not to be construed as an official Department of the Army position unless so designated by other authorized documents.

The products and equipment referred to in this report are not to be considered as an endorsement by the author or the Department of the Army.

REPORT DO	CUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING F
- REPORT NUMBER	2. GOVT ACCESS	ION NO. 3. RECIPIENT'S CATALOG NUMBE
1-77-1		In Final Hent
4. TITLE (and Subtitle)		S. TYPE OF REPORT & PERIOD C
Mass Spectroscopic	Analysis of Polyether ar	nd
Polyurethane Foam	Plastics Degeneration in	
SPH-4 Helmet		6. PERFORMING ORG. REPORT NU
7. AUTHOR(a)		8. CONTRACT OR GRANT NUMBER
Roderick J. McNeil	CPT, MSC	
Frank S. Pettyjohr		
The second secon		
9. PERFORMING ORGANIZATION US Army Aeromedica	1 Research Laboratory	10. PROGRAM ELEMENT, PROJECT AREA & WORK UNIT NUMBERS
(SGRD-UAC), P. O.		
Fort Rucker, Alaba	ma 36362	DD Form 1498
11. CONTROLLING OFFICE NAM	E AND ADDRESS	12. REPORT DATE
	Research Division (SGRD-U	
	al Research Laboratory	13. NUMBER OF PAGES
Fort Rucker, Alaba 14 MONITORING AGENCY NAME	& ADDRESS(II different from Controlling	Office) 15. SECURITY CLASS. (of this repor
	esearch and Development Co	
Washington, DC 20	and the same of th	Unclassified
and the same of th	(12) 1 401	150. DECLASSIFICATION DOWNGR
16. DISTRIBUTION STATEMENT		
		release and sale; its distri
is unlimited.	been approved for public	release and sale, its distil
To diffinited.		
17. DISTRIBUTION STATEMENT	of the abetract entered in Block 20, If dif	ferent from Report)
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reve	rse side if necessary and identify by block	k number)
Aviator helmet		
Chemical solvents		
Mass spectroscopy Gas chromatography		
Gas Cittomatograph		
20. ABSTRACT (Continue on rever	so side if necessary and identify by block	number)
		I-phthalate and ethyl-methyl
		ned in the low gaseous transf
		ne SPH-4 aviator helmet. The
agents are the cause	of the deterioration of t	the SPH-4 helmet polyether an
polyurethane foam lin		

DD FORM 1473 EDITION OF

EDITION OF ! NOV 68 IS OBSOLETE

The use of mass spectrographic and gas chromatographic techniques provided the sampling of chemical compounds contained within the polyethylene bag. The

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (Then Data Entered)

UNCLASSIFIED CURITY CLASSIFICATION OF	THIS P	AGE(Whee	n Data Entered)							
olution to prevent he protective bag.	foam	liner	deterioration	is	to	remove	the	SPH-4	helmet	from

SUMMARY

The United States Army Aeromedical Research Laboratory, through its Life Support Equipment Retrieval Program as directed by Army Regulation 95-5, constantly evaluates all aspects of life support equipment. The deterioration of foam lining material of new SPH-4 aviator helmets was an operational problem identified through the life support equipment program. The application of advanced biomedical mass spectrographic and gas chromatographic technology provided the identification of two chemical compounds causing deterioration of stored SPH-4 helmets. The removal or opening of the polyethylene protective bag will allow offgasing of the chemical compounds developed by the curing process occurring during storage. This study and the simple corrective action will save the United States Army approximately \$122,000 in the salvage of only 10% of SPH-4 helmet stocks and additional inestimable dollars in helmet procurement.

ROBERT W. BATLEY

Colonel, MSC Commanding

MASS SPECTROSCOPIC ANALYSIS OF POLYETHER AND POLYURETHANE FOAM PLASTICS DEGENERATION IN THE SPH-4 HELMET

INTRODUCTION

The Biochemistry Branch of the Aviation Medicine Research Division, US Army Aeromedical Research Laboratory (USAARL), through coordination with the Bioengineering and Life Support Equipment Division, USAARL, evaluated the problem of deterioration of the SPH-4 aviator helmet (Federal Stock Numbers 8415-00-144-4985 and 8415-00-144-4981) foam lining material. The Life Support Equipment Branch, through the Life Support Equipment Retrieval Program (AR 95-5) and continuing evaluation of life support equipment, had found the foam lining material of new SPH-4 aviator helmets in the original storage condition to be unserviceable. The SPH-4 was sealed in a polyethylene protective bag at the time of manufacture. To evaluate the possibility of liquid or gas solvent contamination at the time of production, a mass spectroscopic analysis of the plastic foam, associated polymers, and contents of plastic protective bag was undertaken.

MATERIALS AND METHODS

The SPH-4 contains polyether and polyurethane foam in the helmet liner and ear cups. The ear cup liners are contained in a polyvinyl ear seal. An unopened SPH-4 helmet was obtained in its original plastic protective container, Lot Number 97427, sealed in June 1970.

Analysis and identification of major components were accomplished by use of JEOL DMS 100-231/241 Mass Spectrometer and Hewlett Packard 5714 Gas Chromatograph (MS-GC). Gas samples from the protective liner were withdrawn and injected onto two meter, two millimeter (mm), OV-1 column isothermal at $60^{\circ}C$. Helium (He) was utilized as the carrier gas at 12 milliliters per minute (ml/min). The MS utilized the following conditions:

Separator 100°C, two stage; ion chamber 120°C; ionizing voltage 75eV, regulated; ionizing current 300 μ A; and mass range 0-300, 10 seconds/decade.

Data were analyzed by elemental mapping and computerized mass marking. Spectral information was confirmed using manual interpretation of a Varian Mass Spectrometer at 180°C inlet scanning at 10 Atomic Mass Units (AMU)/minute mass 15 through 350.

RESULTS

Samples were from SPH-4 helmet, Lot Number 97427, sealed in June 1970.

Capillary leak of 200 μ liter ($\mu 1)$ from two liter flask at 20 micron revealed all masses present to be less than 300 on five minute scan from 0-800 at resolutions of greater than 5000.

The total ion current (TIC) study demonstrated four components in addition to normal atmospheric constituents with retention index (RI) from 1:12 to 2:29 (Table I).

TABLE I
SUMMARY OF MASS SPECTROGRAPHIC ANALYSIS

COMPONENT	PEAK NUMBER	RI	PARENT MOLECULAR ION
di-n-butyl phthalate	1	1:12	278
n-butyl phthalate	2	1:37	160
ethyl-methyl ketone	3	1:44	72
n-methyl amino	4	2:29	31

RI = Retention Index

Components 2 and 3 are present in sufficient concentration at the time of sampling to create a decomposition potential. Peak 4 was at the limit of flame ionization detectability (FID) at 4×10^{-11} .

DISCUSSION

Potential sources of chemical attack against the polyether and polyurethane foam contained in the SPH-4 aviator helmet were considered. The possibility a solvent present in the storage area penetrated the plastic liner is considered improbable. The very low gaseous transfer coefficient of the polyethylene of the helmet ear cups would require extremely high levels of solvents for a prolonged period to attack the polyether foam ear cup pads which had deteriorated. This would require an exterior solvent capable of penetrating two dissimilar, low transfer coefficient polymers.

The most probable cause was that the solvent was present in helmet construction at the time of sealing in the polyethylene protective bag. Retention of solvent or catalyst during completion of curing or thermal cycling during storage could result in extremely high solvent concentrations disrupting the polymer structure of the foam.

Following identification of the major helmet foam components, gas samples from a sealed helmet were analyzed using multiple ion matching Mass Spectrometer (MS) techniques. Four peaks were defined as shown in Table I. Peak 1, di-n-butyl phthalate, and Peak 4, n-methyl amino, are common off-gasing products in plastic polymerization indicating that cure was incomplete at the time the helmets were sealed. Peak 2, n-butyl phthalate, is used in polyvinylchloride (PVC) plastics such as the ear seals. Peak 3, ethyl-methyl ketone, is used as a catalyst with fiberglass resins such as the SPH-4 helmet shell. Components 2 and 3 are present in sufficient concentration to effect decomposition of the polyether and polyurethane foam liners of the SPH-4 helmet by containment within a sealed, extremely low gas transfer coefficient polyethylene protective bag. Additionally, the effects of heat during storage could create further off-gasing of the agents.

Solution to the problem is extremely simple:

- a. Provide holes in the present polyethylene protective bag to allow off-gasing of the gaseous products of the curing process.
 - b. Discontinue the use of protective bags.

The cost benefits of this technique to the US Army are calculated as follows:

7,170 SPH-4 helmets currently in stock (Oct 1976) X \$170.00 per helmet = \$1,218,900.00 investment.

The loss of only 10% of the helmet stock would cost:

 $(10\% \times 7,170 \times $170.00) = $121,890.00$

Eliminate polyethylene protective bag (FSN 8105-00-104-9850), cost per bag x total helmets: 7,170 X \$0.07 per bag = \$504.00 savings.

Thus, the total savings realized by this evaluation considering only 10% of helmet stock and elimination of bag would equal \$122,394.00.

RECOMMENDATIONS

- 1. All SPH-4 aviator helmets currently in stock should be removed from, or the seal broken with numerous holes placed in a loosely wrapped polyethylene protective bag.
- 2. In future manufacture, the helmet should be placed in highly porous, unsealed protective material.

DISTRIBUTION LIST OF USAARL REPORTS

Number of Copies	
5	HQDA (SGRD-RP)
	WASH DC 20314
12	Defense Documentation Center
	Alexandria, VA 22314
1	US Army Combat Developments Command
	Medical Department Agency, BAMC
	Fort Sam Houston, TX 78234

			125	200	20
			Chemical Solvents	Mass Spectroscopy	4. Gas Chromatograph
			5		12
		**	2	00	740
		Aviator Helme	-	Č.	0
	142			94:	64
	A-4	9		4.0	20
	NA.	LA.	prig.	N.	5
	NCLASSIE	he	12	à	in
	5	40	73	105	
		-3	87.	20	
	2	3		7	100
		45.		200	
		p=4	OI.	100	
-1					
	3	35			
	. 23		2		
	10.	in.			
	12		20	4	12
					S.
	VC.	22			16.
					1996
			-34		8
	261	220	4	3.30	
	-82		14	0	
			10		85
	:8		-72		12
	280	X	2	#	-52
	63			-	154
	34		15	. 1	- 20
	.0	3	8		3
	1		5-		
		846	381		. 5
5	120		3,	- 44	96
	177				
	81				
	35	25		2	
	1.50		17		2
			÷		-
	14				: 65
		B			
					-
				6.7	100
				100	
	12	S SPECTROSCOPIC ANALYSIS OF POLYETHER AND POLYERITHANE FOAM	58	8	A76,758A 819, Aviation Medicine Research Division.
	1.5		-		
	1.9	45			
	196		-20		
				36	86
	18				
			3		
				1	
	190				
	ΙØ				
		19			
	10	150			
				5	
	Army Assomettral Research Lahoratory, Fort Rucker, Alabana		PLASTICS DECENDENTION IN THE SPH-4 WELMET by Roderick J. McNet	CPT, MSC, and Frank S. Pettyjohn, M.D., LTC, MC, 9 pp. DA	
		8			

The components of plastic manufacture, n-buryl-phthalate and contained in the low gaseous transfer mentalized why backly, are been found in Mag contentrations contained in the low gaseous transfer of the properties of the special part of the course of the described in the SPH-4 whence polyarcher and polyarchane feas inding material. The use of many special contents and polyarchane feas inding material. The use of many special contents are the polyarchy encourse provided the sampling of the manufacture and polyarchy encourse. The solution to prevent foam liner determination is in remove the SPH-4 helmet from the protective bag.

A text Accounted tail Research Laboratory, port Bucker, Alabama, NASARSTREAD WASSESTREAD WASSESTREAD WASSESTREAD WAS SPECTROSCOPIC ANALYSIS OF POLYTERER AND POLYMETHER FOAM. 1. Aviator Helmat Transport of the Analysis of the State of the Analysis of the Analysis of the State of the Analysis of the State of the Analysis of the Analysis of the State of the Analysis of the State of State of State of the State of State o	NUCLASSIFIED WICHASSIFIED Aviator Helmer Chemical Solvents Hass Spectroscopy Cas Chromatography Cas Chromatography In the low gasebus transfer In the low gasebus are the cause militing material: rowided the sampling of n to prevent foam liner
ARE 77-1 MICLASSIFIED MASS SPECIFORCOOPE ARALYSIS OF POLYETERS AND POLYBETHANE POAK MASS SPECIFORCOOPE ARALYSIS OF POLYBETHANE POAK PLASTICS DEGREEATION IN THE SPH-4 HILMET by Rederick J. McMell, PLASTICS DEGREEATION IN THE SPH-4 HILMET by Rederick J. McMell, PLASTICS DEGREEATION IN THE SPH-4 HILMET by Rederick J. McMell, PRO SECTION OF THE SPH-4 HILMET BY REDERICK SOOPY PRO SECTION OF THE SPH-4 HILMET BY AND THE SOURCE SOOPY AND SECTION OF THE SPH-4 HILMET BY AND THE SOURCE SOOPY AND SECTION OF THE SPH-4 HILMET BY AND THE SPECIFORM OF THE SPECIFORM OF THE SPH-4 HILMET BY THE SPECIFORM OF THE SPH-4 WILLED THE BREET THE SPECIFORM OF THE	UNCLASSIFIED Avior Helset Chemical Solvents Gas Chromatography in the low gaseous fransfer Those agents are the cause Thing material.

